




Job Number	100345154[1]
Playground	Castle Dene Playground
Date and Time of Inspection	02 September 2025 12:34:18
Inspecting Officer	John Rutherford
Signature	

INSPECTION FINDINGS - Minor Defect, requires monitoring

Question	Response
Equipment Long Description	Large climbing frame with slide and surface
Equipment Reference	NCC001-PLAYEQ-PGPRU001_006
Equipment Make	SUTCLIFFE
Equipment status	Minor defect, requires monitoring
Detail of defect	sections of surface missing and loose
Risk of the defect causing injury	1 - Very low - Extremely unlikely, minimal probability
Possible severity of injury caused by defect	1 - Very low - No injury likely, scratches at the most
Date of Inspection	02/09/2025

INSPECTION FINDINGS - Minor Defect, requires monitoring

Question	Response
Equipment Long Description	Spinner
Equipment Reference	NCC001-PLAYEQ-PGPRU001_007
Equipment Make	SUTCLIFFE
Equipment status	Minor defect, requires monitoring
Detail of defect	rubber stopper missing from the top
Risk of the defect causing injury	1 - Very low - Extremely unlikely, minimal probability
Possible severity of injury caused by defect	1 - Very low - No injury likely, scratches at the most
Date of Inspection	02/09/2025

INSPECTION FINDINGS - Minor Defect, requires monitoring

Question	Response
Equipment Long Description	Nest Swing and surface
Equipment Reference	NCC001-PLAYEQ-PGPRU001_008
Equipment Make	SUTCLIFFE
Equipment status	Minor defect, requires monitoring
Detail of defect	shackle missing
Risk of the defect causing injury	1 - Very low - Extremely unlikely, minimal probability
Possible severity of injury caused by defect	1 - Very low - No injury likely, scratches at the most
Date of Inspection	02/09/2025

INSPECTION FINDINGS - Removed

Question	Response
Equipment Long Description	Infant Swings with surface
Equipment Reference	NCC001-PLAYEQ-PGPRU001_002
Equipment status	Equipment Removed - Temporary
Detail of defect	rubber splitting. Leg divider missing. swing has been taken down
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	02/09/2025

INSPECTION FINDINGS - Removed

Question	Response
Equipment Long Description	Tyre Swing and surface
Equipment Reference	NCC001-PLAYEQ-PGPRU001_009
Equipment status	Equipment Removed - Temporary
Detail of defect	chain links wearing thin
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	02/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Seat
Equipment Reference	NCC001-PLAYEQ-PGPRU001_001
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	02/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Double seat Springer with surface
Equipment Reference	NCC001-PLAYEQ-PGPRU001_003
Equipment Make	SUTCLIFFE
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	02/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Climbing Frame with slide and surface

Equipment Reference	NCC001-PLAYEQ-PGPRU001_004
Equipment Make	SUTCLIFFE
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	02/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Single Seat Springer with surface
Equipment Reference	NCC001-PLAYEQ-PGPRU001_005
Equipment Make	SUTCLIFFE
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	02/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Fence with gates
Equipment Reference	NCC001-PLAYEQ-PGPRU001_010
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	02/09/2025


INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Signs (3)
Equipment Reference	NCC001-PLAYEQ-PGPRU001_011
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury

Possible severity of injury caused by defect	5 - Very high - Very severe injury, amputation, loss of sight, permanent disablement, death
Date of Inspection	02/09/2025

End of Report



Job Number	100345158[1]
Playground	Highfield Playground
Date and Time of Inspection	03 September 2025 09:55:12
Inspecting Officer	John Rutherford
Signature	

INSPECTION FINDINGS - Minor Defect, requires monitoring

Question	Response
Equipment Long Description	Nest Swing and surface
Equipment Reference	NCC001-PLAYEQ-PGPRU005_003
Equipment Make	SUTCLIFFE
Equipment status	Minor defect, requires monitoring
Detail of defect	swing frame loose.
Risk of the defect causing injury	1 - Very low - Extremely unlikely, minimal probability
Possible severity of injury caused by defect	1 - Very low - No injury likely, scratches at the most
Date of Inspection	03/09/2025

INSPECTION FINDINGS - Minor Defect, requires monitoring

Question	Response
Equipment Long Description	Zipline & surface
Equipment Reference	NCC001-PLAYEQ-PGPRU005_001
Equipment Make	SUTCLIFFE
Equipment status	Minor defect, requires monitoring
Detail of defect	rubber step cover missing
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	03/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Swings and surface
Equipment Reference	NCC001-PLAYEQ-PGPRU005_002
Equipment Make	SUTCLIFFE
Equipment status	Satisfactory
Detail of defect	seats splitting
Risk of the defect causing injury	1 - Very low - Extremely unlikely, minimal probability
Possible severity of injury caused by defect	1 - Very low - No injury likely, scratches at the most
Date of Inspection	03/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Space Net and surface
Equipment Reference	NCC001-PLAYEQ-PGPRU005_004
Equipment Make	TAYPLAY
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	03/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Spinning Dish and surface
Equipment Reference	NCC001-PLAYEQ-PGPRU005_005
Equipment Make	SUTCLIFFE
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	03/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Multi Climbing Frame and surface
Equipment Reference	NCC001-PLAYEQ-PGPRU005_006
Equipment Make	SUTCLIFFE
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	03/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Seats, Picnic Benches (17)
Equipment Reference	NCC001-PLAYEQ-PGPRU005_007
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	03/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Fencing - Gates

Equipment Reference	NCC001-PLAYEQ-PGPRU005_008
Equipment status	Satisfactory
Detail of defect	Green gates at both play areas won't close on they own,Springs needs adjusting
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	03/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Skate Park
Equipment Reference	NCC001-PLAYEQ-PGPRU005_009
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	03/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Bins (3)
Equipment Reference	NCC001-PLAYEQ-PGPRU005_010
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	03/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Signs (5)
Equipment Reference	NCC001-PLAYEQ-PGPRU005_011
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury

Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	03/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Infant Swings and surface
Equipment Reference	NCC001-PLAYEQ-PGPRU005_012
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	03/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Infant Mini Roundabout and surface
Equipment Reference	NCC001-PLAYEQ-PGPRU005_013
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	03/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Infant Rocker and surface
Equipment Reference	NCC001-PLAYEQ-PGPRU005_014
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	03/09/2025

INSPECTION FINDINGS - Satisfactory


Question	Response
Equipment Long Description	Infant Multi Climbing Frame and surface
Equipment Reference	NCC001-PLAYEQ-PGPRU005_015
Equipment status	Satisfactory
Detail of defect	small amount of graffiti
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	03/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	General Surface
Equipment Reference	NCC001-PLAYEQ-PGPRU005_016
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	03/09/2025

End of Report



Job Number	100345163[1]
Playground	The Copse Playground
Date and Time of Inspection	02 September 2025 12:39:53
Inspecting Officer	John Rutherford
Signature	

INSPECTION FINDINGS - Minor Defect, requires monitoring

Question	Response
Equipment Long Description	Climbing Frame
Equipment Reference	NCC001-PLAYEQ-PGPRU010_003
Equipment status	Minor defect, requires monitoring
Detail of defect	wood on bridge starting to rot.
Risk of the defect causing injury	1 - Very low - Extremely unlikely, minimal probability
Possible severity of injury caused by defect	1 - Very low - No injury likely, scratches at the most
Date of Inspection	02/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Signs (3)
Equipment Reference	NCC001-PLAYEQ-PGPRU010_001
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	02/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Fence with gate
Equipment Reference	NCC001-PLAYEQ-PGPRU010_002
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	02/09/2025

INSPECTION FINDINGS - Satisfactory


Question	Response
Equipment Long Description	Bin
Equipment Reference	NCC001-PLAYEQ-PGPRU010_004
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	02/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Seat
Equipment Reference	NCC001-PLAYEQ-PGPRU010_005
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	02/09/2025

End of Report



Job Number	100345164[1]
Playground	West Mickley Playground
Date and Time of Inspection	04 September 2025 08:51:13
Inspecting Officer	John Rutherford
Signature	

INSPECTION FINDINGS - Item unsafe, immediate action required

Question	Response
Equipment Long Description	Climbing Frame with slide
Equipment Reference	NCC001-PLAYEQ-PGPRU011_011
Equipment Make	HAGS
Equipment status	Item unsafe, immediate action required
Detail of defect	wooden floor rotten
Risk of the defect causing injury	4 - High - An accident is likely and foreseeable without any added factor
Possible severity of injury caused by defect	3 - moderate - Injury requiring visit to GP or hospital. Fractures, lacerations, sprain
Date of Inspection	04/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Bin
Equipment Reference	NCC001-PLAYEQ-PGPRU011_001
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	04/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Signs (3)
Equipment Reference	NCC001-PLAYEQ-PGPRU011_002
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	04/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Fence with gates
Equipment Reference	NCC001-PLAYEQ-PGPRU011_003
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	04/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Picnic table and bench
Equipment Reference	NCC001-PLAYEQ-PGPRU011_004
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	04/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Multi play frame
Equipment Reference	NCC001-PLAYEQ-PGPRU011_005

Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	04/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Bandstand
Equipment Reference	NCC001-PLAYEQ-PGPRU011_006
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	04/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Infant Swings
Equipment Reference	NCC001-PLAYEQ-PGPRU011_007
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	04/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Swings
Equipment Reference	NCC001-PLAYEQ-PGPRU011_008
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	04/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Roundabout with surface
Equipment Reference	NCC001-PLAYEQ-PGPRU011_009
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	04/09/2025

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Seesaw
Equipment Reference	NCC001-PLAYEQ-PGPRU011_010
Equipment Make	PLAY&LEIS
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	04/09/2025

End of Report