




Job Number	100368056[1]
Playground	Castle Dene Playground
Date and Time of Inspection	01 April 2026 15:22:56
Inspecting Officer	John Rutherford
Signature	

INSPECTION FINDINGS - Minor Defect, requires monitoring

Question	Response
Equipment Long Description	Large climbing frame with slide and surface
Equipment Reference	NCC001-PLAYEQ-PGPRU001_006
Equipment Make	SUTCLIFFE
Equipment status	Minor defect, requires monitoring
Detail of defect	sections of surface missing and loose
Risk of the defect causing injury	1 - Very low - Extremely unlikely, minimal probability
Possible severity of injury caused by defect	1 - Very low - No injury likely, scratches at the most
Date of Inspection	01/04/2026

INSPECTION FINDINGS - Minor Defect, requires monitoring

Question	Response
Equipment Long Description	Spinner
Equipment Reference	NCC001-PLAYEQ-PGPRU001_007
Equipment Make	SUTCLIFFE
Equipment status	Minor defect, requires monitoring
Detail of defect	rubber stopper missing from the top
Risk of the defect causing injury	1 - Very low - Extremely unlikely, minimal probability
Possible severity of injury caused by defect	1 - Very low - No injury likely, scratches at the most
Date of Inspection	01/04/2026

INSPECTION FINDINGS - Minor Defect, requires monitoring

Question	Response
Equipment Long Description	Nest Swing and surface
Equipment Reference	NCC001-PLAYEQ-PGPRU001_008
Equipment Make	SUTCLIFFE
Equipment status	Minor defect, requires monitoring
Detail of defect	shackle missing
Risk of the defect causing injury	1 - Very low - Extremely unlikely, minimal probability
Possible severity of injury caused by defect	1 - Very low - No injury likely, scratches at the most
Date of Inspection	01/04/2026

INSPECTION FINDINGS - Removed

Question	Response
Equipment Long Description	Infant Swings with surface
Equipment Reference	NCC001-PLAYEQ-PGPRU001_002
Equipment status	Equipment Removed - Temporary
Detail of defect	rubber splitting. Leg divider missing. swing has been taken down
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	01/04/2026

INSPECTION FINDINGS - Removed

Question	Response
Equipment Long Description	Tyre Swing and surface
Equipment Reference	NCC001-PLAYEQ-PGPRU001_009
Equipment status	Equipment Removed - Temporary
Detail of defect	chain links wearing thin
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	01/04/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Climbing Frame with slide and surface
Equipment Reference	NCC001-PLAYEQ-PGPRU001_004
Equipment Make	SUTCLIFFE
Equipment status	Satisfactory
Detail of defect	deliberate damage to wet pour surface, trip hazard
Risk of the defect causing injury	1 - Very low - Extremely unlikely, minimal probability
Possible severity of injury caused by defect	1 - Very low - No injury likely, scratches at the most
Date of Inspection	01/04/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Seat
Equipment Reference	NCC001-PLAYEQ-PGPRU001_001
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	01/04/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
----------	----------

Equipment Long Description	Double seat Springer with surface
Equipment Reference	NCC001-PLAYEQ-PGPRU001_003
Equipment Make	SUTCLIFFE
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	01/04/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Single Seat Springer with surface
Equipment Reference	NCC001-PLAYEQ-PGPRU001_005
Equipment Make	SUTCLIFFE
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	01/04/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Fence with gates
Equipment Reference	NCC001-PLAYEQ-PGPRU001_010
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	01/04/2026

INSPECTION FINDINGS - Satisfactory


Question	Response
Equipment Long Description	Signs (3)
Equipment Reference	NCC001-PLAYEQ-PGPRU001_011
Equipment status	Satisfactory

Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	01/04/2026

End of Report



Job Number	100367676[1]
Playground	Highfield Playground
Date and Time of Inspection	26 March 2026 11:51:30
Inspecting Officer	Ross Quinn

Signature	
------------------	--

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Swings and surface
Equipment Reference	NCC001-PLAYEQ-PGPRU005_002
Equipment Make	SUTCLIFFE
Equipment status	Satisfactory
Detail of defect	seats splitting
Risk of the defect causing injury	1 - Very low - Extremely unlikely, minimal probability
Possible severity of injury caused by defect	1 - Very low - No injury likely, scratches at the most
Details of action taken	Monitor
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Zipline & surface
Equipment Reference	NCC001-PLAYEQ-PGPRU005_001
Equipment Make	SUTCLIFFE
Equipment status	Satisfactory
Detail of defect	rubber step cover replaced

Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Reference	NCC001-PLAYEQ-PGPRU005_003
Equipment Make	SUTCLIFFE
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Details of action taken	Shackles have been replaced, secondary chains fixed
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Space Net and surface
Equipment Reference	NCC001-PLAYEQ-PGPRU005_004
Equipment Make	TAYPLAY
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Spinning Dish and surface
Equipment Reference	NCC001-PLAYEQ-PGPRU005_005
Equipment Make	SUTCLIFFE
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury

Date of Inspection	26/03/2026
--------------------	------------

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Multi Climbing Frame and surface
Equipment Reference	NCC001-PLAYEQ-PGPRU005_006
Equipment Make	SUTCLIFFE
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Seats, Picnic Benches (17)
Equipment Reference	NCC001-PLAYEQ-PGPRU005_007
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Fencing - Gates
Equipment Reference	NCC001-PLAYEQ-PGPRU005_008
Equipment status	Satisfactory
Detail of defect	Green gates at both play areas won't close on they own,Springs needs adjusting
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Skate Park
Equipment Reference	NCC001-PLAYEQ-PGPRU005_009
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Bins (3)
Equipment Reference	NCC001-PLAYEQ-PGPRU005_010
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Signs (5)
Equipment Reference	NCC001-PLAYEQ-PGPRU005_011
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Infant Swings and surface
Equipment Reference	NCC001-PLAYEQ-PGPRU005_012
Equipment status	Satisfactory

Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Infant Mini Roundabout and surface
Equipment Reference	NCC001-PLAYEQ-PGPRU005_013
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Infant Rocker and surface
Equipment Reference	NCC001-PLAYEQ-PGPRU005_014
Equipment status	Satisfactory
Detail of defect	Rocker replaced
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory


Question	Response
Equipment Long Description	Infant Multi Climbing Frame and surface
Equipment Reference	NCC001-PLAYEQ-PGPRU005_015
Equipment status	Satisfactory
Detail of defect	small amount of graffiti
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	General Surface
Equipment Reference	NCC001-PLAYEQ-PGPRU005_016
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

End of Report



Job Number	100367681[1]
Playground	The Copse Playground
Date and Time of Inspection	26 March 2026 09:22:13
Inspecting Officer	Ross Quinn
Signature	

INSPECTION FINDINGS - Minor Defect, requires monitoring

Question	Response
Equipment Long Description	Climbing Frame
Equipment Reference	NCC001-PLAYEQ-PGPRU010_003
Equipment status	Minor defect, requires monitoring
Detail of defect	wood on bridge starting to rot, also very slippery - slip/trip hazard
Risk of the defect causing injury	2 - Low - Little chance of an accident, low probability
Possible severity of injury caused by defect	2 - low - Minor injuries, cuts, bruises, some first aid may be necessary
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Signs (3)
Equipment Reference	NCC001-PLAYEQ-PGPRU010_001
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Fence with gate
Equipment Reference	NCC001-PLAYEQ-PGPRU010_002
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory


Question	Response
Equipment Long Description	Bin
Equipment Reference	NCC001-PLAYEQ-PGPRU010_004
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Seat
Equipment Reference	NCC001-PLAYEQ-PGPRU010_005
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

End of Report



Job Number	100367682[1]
Playground	West Mickley Playground
Date and Time of Inspection	26 March 2026 12:37:12
Inspecting Officer	Ross Quinn
Signature	

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Bin
Equipment Reference	NCC001-PLAYEQ-PGPRU011_001
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Signs (3)
Equipment Reference	NCC001-PLAYEQ-PGPRU011_002
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Fence with gates
Equipment Reference	NCC001-PLAYEQ-PGPRU011_003
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Picnic table and bench
Equipment Reference	NCC001-PLAYEQ-PGPRU011_004
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Multi play frame
Equipment Reference	NCC001-PLAYEQ-PGPRU011_005
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Bandstand
Equipment Reference	NCC001-PLAYEQ-PGPRU011_006
Equipment status	Satisfactory

Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Infant Swings
Equipment Reference	NCC001-PLAYEQ-PGPRU011_007
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Swings
Equipment Reference	NCC001-PLAYEQ-PGPRU011_008
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Roundabout with surface
Equipment Reference	NCC001-PLAYEQ-PGPRU011_009
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Seesaw
Equipment Reference	NCC001-PLAYEQ-PGPRU011_010
Equipment Make	PLAY&LEIS
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

INSPECTION FINDINGS - Satisfactory

Question	Response
Equipment Long Description	Climbing Frame with slide
Equipment Reference	NCC001-PLAYEQ-PGPRU011_011
Equipment Make	HAGS
Equipment status	Satisfactory
Risk of the defect causing injury	0 - No risk of injury
Possible severity of injury caused by defect	0 - No possible severity of injury
Date of Inspection	26/03/2026

End of Report