

Play Area/Item	Standard Achieved RoSPA 2022	NCC Inspections 2023	Notes
		Mar	
Castledene			
Fencing	n/a	√	
Gate	n/a	√	
Seating	n/a	√	
Signage	n/a	√	
Signage (Covid)	n/a	√	
Surface - Tarmac	n/a	√	
Basket Swing	√	√	
Swing - Cantilever - Tyre	X	√	
Swing - Toddler - 1 Bay 2 Seat	√	√	Rubber splitting monitoring required, replace?
Multitplay Junior	√	√	
Multitplay Toddler	√	√	
Rocker - Ladybird	√	√	
Rocker - Seesaw	√	√	
Rotator - Pirouette	√	√	
Goal Post - Football			
Play Area/Item	Standard Achieved RoSPA 2022	NCC Inspections 2023	Notes
		Mar	
The Copse			
Litter Bin	√	√	
Fencing	n/a	√	
Gate	√	√	
Seating	n/a	√	
Signage	n/a	√	
Signage (Covid)	n/a	√	
Surface - Grass	n/a		
Planting - Trees	n/a		
Multiplay - Toddler	√	√	Wood on bridge beginning to rot, replace?

Play Area/Item	Standard Achieved RoSPA 2022	NCC Inspections 2023	Notes
		Mar	
Highfield Park			
Seats	n/a	√	
Signage	n/a	√	
Signage (covid)	n/a	√	
Fencing in Junior Play	n/a	√	
Gates in Junior Play	n/a	√	
General Surface	n/a	√	
Litter Bin	n/a	√	
Cableway	√	√	
Carousel/Black & Yellow	√	√	
Space Net	√	√	
Swing - Mixed - 2 Bay 1 Basket 2 Junior Seat	√	√	Seats splitting and small hole in surface, repair or replace. Nest swing flame loose.
Swing - Toddler - 1 Bay 2 Seat	√	√	
Carousel/Space dish	√	√	
Multiplay - Junior	X	√	
Multiplay - Toddler	√	√	
Rocker - Ladybird	√	√	
Goal Post - Football			

Play Area/Item	Standard Achieved RoSPA 2022	NCC Inspections 2023	Notes			
		Mar				
Highfield Skatepark						
Skatepark	Installed after this inspection	√				
Play Area/Item	Standard Achieved RoSPA 2022	NCC	Notes			
		Mar				
West Mickley						
Litter Bin	√	√				
Fencing	n/a	√				
Gate	√	√				
Surface	n/a	√				
Seating	n/a	√				
Signage	n/a	√				
Signage (covid)	n/a	√				
Shelter	n/a	√				
Agility - Balance Activity Trail	√	√				
Rocker - Seesaw	√	√				
Swing - Toddler - 1 Bay 2 Seat	√	√				
Swing - Junior - 1 Bay 2 Seat	√	√				
Carousel	√	√				
Multiplay	√	√				
Goal Post - Football	X					